Document Title	SWS_ADCDriver: Complete Change Documentation 4.3.0 - 4.3.1
Document Owner	AUTOSAR
Document Responsibility	AUTOSAR
Document Identification No	695

Document Status	Final
Part of AUTOSAR Standard	Classic Platform
Part of Standard Release	4.3.1

Table of Contents

1 SWS_ADCDriver

1.1 Specification Item SWS_Adc_00112

Trace References:

SRS_BSW_00386, SRS_SPAL_12448

Content:

If development error detection for the ADC module is enabled: if called

called while not all groups are either in state ADC_IDLE or state ADC_STREAM_COMPLETED, while no conversion is ongoing (ADC groups which are implicitly stopped), the function Adc_DeInit shall raise development errorADC_E_BUSY and return without any actionreport a runtime error.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of 'Runtime errors'

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-

  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

  SWS_LinIf:

———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.2 Specification Item SWS_Adc_00215

Trace References:

SRS_Adc_12802

Content:

If development error detection for the ADC module is enabled: when When called while the group status is ADC_IDLE and the group conversion was not started (no results are available from previous conversions) , the function Adc_GetStreamLastPointer shall raise development report a runtime error ADC_E_IDLE, set the pointer, passed as parameter (PtrToSamplePtr), to NULL and return 0. .

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

Notes:
- It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.3 Specification Item SWS_Adc_00241

Trace References:

SRS_BSW_00323, SRS_BSW_00386, SRS_SPAL_12448

Content:

If development error detection for the ADC module is enabled: when When called while the group is in state ADC_IDLE, the function Adc_StopGroupConversion shall raise development report a runtime error ADC_E_IDLEand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-
  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

  SWS_LinIf:
  ———-
  SWS_LinIf_00359: add Det_ReportRuntimeError

  SWS_UdpNm:
  ———-
  Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

  *** ECUC XML ***
  Not affected. No configuration of runtime error reporting required (see SWS BSW

General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.4 Specification Item SWS_Adc_00304

Trace References:

none

Content:

If development error detection for the ADC module is enabled: if the the group is not enabled (with a previous call of Adc_EnableHardwareTrigger), the function Adc_DisableHardwareTrigger shall raise development report a runtime error ADC_E_IDLEand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-

Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.5 Specification Item SWS_Adc_00321

Trace References:

none

Content:

If development error detection is enabled for the ADC driver and if the the priority mechanism is disabled and queuing disabled: when called while any group with trigger source SW is not in state ADC_IDLE, the function Adc_EnableHardwareTrigger shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

Agreed solution:

solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

Notes:
- It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.6 Specification Item SWS_Adc_00346

Trace References:

none

Content:

If development error detection for the ADC module is enabled and the the priority mechanism is disabled and the queuing is disabled : when called while any of the groups, which can not be implicitly stopped, is not in state ADC_IDLE , the function Adc_StartGroupConversion shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-
  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

  SWS_LinIf:
  ———-
  SWS_LinIf_00359: add Det_ReportRuntimeError

  SWS_UdpNm:
  ———-
  Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.7 Specification Item SWS_Adc_00348

Trace References:

none

Content:

If development error detection for the ADC module is enabled and the the priority mechanism is enabled: when called while a group, which can not be implicitly stopped, is not in state ADC_IDLE, the function Adc_StartGroupConversion shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of 'Runtime errors'

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.8 Specification Item SWS_Adc_00349

Trace References:

none

Content:

If development error detection for the ADC module is enabled: if the the HW trigger for the group is already enabled, the function Adc_EnableHardwareTrigger shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

Inconsistencies in SWS with semantics of Default errors
–Last change on issue 59085 comment 26–

Agreed solution:

solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

Notes:
- It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.9 Specification Item SWS_Adc_00351

Trace References:

none

Content:

If development error detection for the ADC module is enabled and the the priority mechanism is disabled and the queuing is enabled: when called while a group, which can not be implicitly stopped, is not in state ADC_IDLE, the function Adc_StartGroupConversion shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of 'Runtime errors'

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-
  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

  SWS_LinIf:
  ———-
  SWS_LinIf_00359: add Det_ReportRuntimeError

  SWS_UdpNm:

———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.10 Specification Item SWS_Adc_00353

Trace References:

none

Content:

If development error detection for the ADC module is enabled: if the the maximum number of available hardware triggers is already enabled (device and implementation specific), the function Adc_EnableHardwareTrigger shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.

- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.11 Specification Item SWS_Adc_00369

Trace References:

none

Content:

Service name:	Adc_ReadGroupAdc_ReadGroup
Syntax:	Std_ReturnType Adc_ReadGroup(Adc_GroupType Group, Adc_ValueGroupType* DataBufferPtr)
Service ID[hex]:	0x04
Sync/Async:	Synchronous

Reentrancy:	Reentrant	
Parameters (in):	GroupAdc_ReadGroup.Group	Numeric ID of requested ADC channel group.
Parameters (inout):	None	
Parameters (out):	DataBufferPtrAdc_ReadGroup.Data BufferPtr	ADC results of all channels of the selected group are stored in the data buffer addressed with the pointer.
Parameters (inout):	None	
Parameters (out):	None	
Return value:	Std_ReturnType	E_OK: results are available and written to the data buffer E_NOT_OK: no results are available or development error occured
Description:	Reads the group conversion result of the last completed conversion round of the requested group and stores the channel values starting at the DataBufferPtr address. The group channel values are stored in ascending channel number order (in contrast to the storage layout of the result buffer if streaming access is configured).	

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #68035: [diverse] Introduce rules defining which input parameters shall be passed per value and which ones per const reference

  Problem description:

  SWS_BSW_00186 especially states that input pointer parameters shall use the const qualifier (i.e., shall be P2CONST).

  In addition to that there shall be a SWS item that states that input parameters of integral and enum type shall be passed by value whereas input parameters of structure type shall be passed by reference.

  The various transformer SWS documents shall be adapted accordingly.
  –Last change on issue 68035 comment 4–

  Agreed solution:

  BSW UML model
  ————-

  The attachment "Changed Proposal in WP-A meeting" contains a list of changes to the APIs in the model (see column H). Afterwards all related documents (included in impact list) shall update their
  generated artifacts.

General Requirements on Basic Software Modules
~~~~~~

Introduce the following requirements prior to SRS_BSW_00371:

SRS_BSW_xxxxx: Input parameters of scalar and enum types shall be passed as a value.
Type: valid
Description: All input parameters of scalar or enum type shall be passed as a value.
Rationale:

Use case: For example a function named <Mip>_SomeFunction with a return type of Std_ReturnType and a single parameter named SomeParameter of type uint8 is defined with the following signature:

Std_ReturnType <Mip>_SomeFunction(uint8 SomeParameter);
Dependencies: –
Supporting Material: —

SRS_BSW_yyyyy: Input parameters of structure type shall be passed as a reference to a constant structure
Type: valid
Description: All input parameters of structure type shall be passed as a reference constant structure
Rationale: Passing input parameters of structure type by value would result in additional run-time overhead due to efforts for copying the whole structure.
Use case: For example a function named <Mip>_SomeFunction with a return type of Std_ReturnType and a single parameter named SomeParameter of type SomeStructure (where SomeStructure is a struct) is defined with the following signature:

Std_ReturnType <Mip>_SomeFunction(P2CONST(SomeStructure, AUTOMATIC, <MIP>_APPL_DATA) SomeParameter);
Dependencies: –
Supporting Material: —

SRS_BSW_zzzzz: Input parameters of array type shall be passed as a reference to the constant array base type
Type: valid
Description: All input parameters of array type shall be passed as a reference to the
~~~~~~

constant array base type
Rationale: This effectively matches the behavior specified in the ISO-C:90 namely that a "declaration of a parameter as ’array of type’ shall be adjusted to ’qualified pointer to
type’".
Use case: For example a function named <Mip>_SomeFunction with a return type of Std_ReturnType and a single parameter named SomeParameter of type array of uint8 is defined with the following signature:

Std_ReturnType <Mip>_SomeFunction(P2CONST(uint8, AUTOMATIC, <MIP>_APPL_DATA) SomeParameter);
Dependencies: –
Supporting Material: —

General Specification of Transformers
~~~~~~

In SWS_Xfrm_00036 change

const <type>* dataElement

to

<paramtype> dataElement

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

In SWS_Xfrm_00038 change

[<type> data_1,] ...
[<type> data_n]

to
~~~~~~

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet
"type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

In SWS_Xfrm_00040 change

[<originalData1>, ...
<originalDataN>]

to

[<paramtype> originalData1,] ...
[<paramtype> originalDataN]

and add the following to the where clause after the API table after the bullet
"type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

In SWS_Xfrm_00044 change

<type> *data_1, ...
<type> *data_n

to

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

Speci?cation of SOME/IP Transformer
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

In SWS_SomeIpXf_00138 change

const <type>* dataElement

to

<paramtype> dataElement

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy,
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

In SWS_SomeIpXf_00141 change

[<type> data_1,] ...
[<type> data_n]

to

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

In SWS_SomeIpXf_00145 change

<type> *data_1, ...
<type> *data_n

to

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet

"type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

Specification of COM Based Transformer
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

In SWS_ComXf_00007 change

const <type>* dataElement

to

<paramtype> dataElement

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

Specification of Time Sync over Ethernet
~~~~~~

In SWS_EthTSyn_00040 make the parameter DataPtr of EthTSyn_RxIndication const.

Specification of SWS FlexRay Interface
~~~~~~

Change SWS_FrIf_05073 from
FrIf_NumOfStartupFramesPtr (IN)
to
FrIf_NumOfStartupFramesPtr (OUT)

Specification of ADC
~~~~~~
~[SWS_Adc_00419] Adc_SetupResultBuffer: change Adc_ValueGroupType* to const Adc_ValueGroupType*
~[SWS_Adc_00369] Adc_ReadGroup: move Adc_ValueGroupType * from Parameters (in) to Parameters (out)

There is no need to change parameter from IN to INOUT in Adc_SetupResultBuffer

Specification of Com
~~~~~~
Change type of parameter MetaData of Com_TriggerIPDUSendWithMetaData from uint8* to const uint8*

Specification of ComM
~~~~~~
no change required

Specification of Dem
~~~~~~
no change required

Specification of DLT
~~~~~~
no change required

Specification of DoIP
~~~~~~
From:
Std_ReturnType <User>_DoIPRoutingActivationConfirmation(boolean* Confirmed, uint8* ConfirmationReqData, uint8* ConfirmationResData)
Std_ReturnType <User>_DoIPRoutingActivationAuthentication(boolean* Authentified, uint8* AuthenticationReqData, uint8* AuthenticationResData)

To:
Std_ReturnType <User>_DoIPRoutingActivationConfirmation(boolean* Confirmed, const uint8* ConfirmationReqData, uint8* ConfirmationResData)
Std_ReturnType <User>_DoIPRoutingActivationAuthentication(boolean* Authentified, const uint8* AuthenticationReqData, uint8* AuthenticationResData)

Specification of E2ELibrary
~~~~~~
no change required

Specification of Eth
~~~~~~
no change required

Specification of EthIf
~~~~~~
no change required

Specification of EthSwitchDriver
~~~~~~
no change required

Specification of ICUDriver
~~~~~~
SWS_Icu_00201: Icu_StartTimestamp
Parameter (IN): Icu_ValueType* BufferPtr shall be changed to Parameters (out) type

Specification of LdCom

~~~~~~
[SWS_LDCOM_00027]: LdCom_CopyTxData
BufReq_ReturnType LdCom_CopyTxData(PduIdType id, const PduInfoType* info, RetryInfoType* retry, PduLengthType* availableDataPtr) shall be changed to
BufReq_ReturnType LdCom_CopyTxData(PduIdType id, const PduInfoType* info, const RetryInfoType* retry, PduLengthType* availableDataPtr)

[SWS_LDCOM_00036]: Rte_LdComCbkCopyTxData_<sn>
BufReq_ReturnType Rte_LdComCbkCopyTxData_<sn>(const PduInfoType* info, RetryInfoType* retry, PduLengthType* availableDataPtr) shall be changed to
BufReq_ReturnType Rte_LdComCbkCopyTxData_<sn>(const PduInfoType* info, const RetryInfoType* retry, PduLengthType* availableDataPtr)

Specification of Lin
~~~~~~
PduInfoPtr needs to be const in Std_ReturnType Lin_SendFrame(uint8 Channel, const Lin_PduType* PduInfoPtr)

Specification of PduR
~~~~~~
* PduR_<User:LoTp>CopyTxData
add const to "RetryInfoType* retry"

Specification of J1939Nm
~~~~~~
Change parameter 'name' of User_AddressClaimedIndication to type 'const uint8*'

Specification of SoAd
~~~~~~
=> everything already fixed with RfC 65633

Specification of SPIHandlerDriver
~~~~~~
==> nothing to change for SWS SPI

Specification of SynchronizedTimeBaseManager
~~~~~~
~~~~~~

"StbM not affected. All issues listed in the WP-A attachment have been already implemented by IT 69124 in context of RfC 65633"

Specification of TcpIp
~~~~~~
~[SWS_TCPIP_00040] TcpIp_DhcpReadOption: change DataPtr from (IN) to (OUT)
~[SWS_TCPIP_00189] TcpIp_DhcpV6ReadOption: change DataPtr from (IN) to (OUT)
=> everything else already fixed with RfC 65633

Specification of TimeSyncOverFlexRay
~~~~~~
"Change SWS_FrTSyn_00064: parameter versioninfo of type Std_VersionInfoType* is marked wrongly as IN. Change to OUT"

Specification of EFX
~~~~~~~~~~~~~~~~~~~~~~
~ [SWS_Efx_00355] Efx_Debounce_u8_u8: Include constant for pointer Input-parameter as like below.
uint8 Efx_Debounce_u8_u8(boolean X, Efx_DebounceState_Type * State, const Efx_DebounceParam_Type * Param, sint32 dT)

~ [SWS_Efx_00376] Efx_MedianSort: The parameter <InType>* Array should be InOut instead of In parameter as like below.
Parameters (in): N Size of an array
Parameters (inout): Array Pointer to an array

~ [SWS_Efx_00309] Efx_RampCheckActivity: Include constant for pointer Input-parameter as like below.
boolean Efx_RampCheckActivity(const Efx_StateRamp_Type* State_cpst)

~ [SWS_Efx_00307] Efx_RampGetSwitchPos: Include constant for pointer Input-parameter as like below.
boolean Efx_RampGetSwitchPos(const Efx_StateRamp_Type* State_cpst)

~ [SWS_Efx_00193] Efx_Array_Average: Include constant for pointer Input-parameter as like below.
<OutType> Efx_Array_Average_<InTypeMn>_<OutTypeMn>(const <InType>* Array, uint16 Count)
~~~~~~~~~~~~~~~~~~~~~~

Specification of MFL
~~~~~~~~~~~~~~~~~~~~~~~
~ [SWS_Mfl_00192] Mfl_Debounce_u8_u8: Include constant for pointer Input-parameter as like below.
boolean Mfl_Debounce_u8_u8(boolean X, Mfl_DebounceState_Type* State, const Mfl_DebounceParam_Type* Param, float32 dT)

~ [SWS_Mfl_00266] Mfl_DebounceInit: The parameter Mfl_DebounceState_Type* State should be Out instead of In parameter as like below.
Parameters (in): X Initial value for the input state
Parameters (out): State Pointer to structure for debouncing state variables

~ [SWS_Mfl_00246] Mfl_HystDeltaRight_f32_u8: Include constant for pointer Input-parameter as like below.
boolean Mfl_HystDeltaRight_f32_u8(float32 X, float32 Delta, float32 Rsp, const uint8* State)

~ [SWS_Mfl_00285] Mfl_MedianSort_f32_f32: The parameter Array should be InOut instead of In parameter as like below.
Parameters (in): N Size of an array
Parameters (inout): Array Pointer to an array

~ [SWS_Mfl_00037] Mfl_PT1SetState: The parameter State_cpst should be Out instead of In parameter as like below.
Parameters (in): X1_f32 Initial value for input state
Y1_f32 Initial value for output state
Parameters (out): State_cpst Pointer to internal state structure

~ [SWS_Mfl_00225] Mfl_RampCheckActivity: Include constant for pointer Input-parameter as like below.
boolean Mfl_RampCheckActivity(const Mfl_StateRamp_Type* State_cpst)

~ [SWS_Mfl_00223] Mfl_RampGetSwitchPos: Include constant for pointer Input-parameter as like below.
boolean Mfl_RampGetSwitchPos(const Mfl_StateRamp_Type* State_cpst)
–Last change on issue 68035 comment 135–

BW-C-Level:

Application	Specification	Bus
1	4	1
~~~~~~~~~~~~~~~~~~~~~~~

1.12 Specification Item SWS_Adc_00388

Trace References:

none

Content:

If development error detection for the ADC module is enabled: when When called while the group status is ADC_IDLE and the group conversion was not started (no results are available from previous conversions), the function Adc_ReadGroup shall raise development report a runtime error ADC_E_IDLE, return E_NOT_OK and return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of 'Runtime errors'

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-

  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

  SWS_LinIf:
  ———-

  SWS_LinIf_00359: add Det_ReportRuntimeError

  SWS_UdpNm:

——–

Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.13 Specification Item SWS_Adc_00419

Trace References:

none

Content:

Service name:	Adc_SetupResultBufferAdc_SetupResultBuffer	
Syntax:	Std_ReturnType Adc_SetupResultBuffer(Adc_GroupType Group, const Adc_ValueGroupType* DataBufferPtr)	
Service ID[hex]:	0x0c	
Sync/Async:	Synchronous	
Reentrancy:	Reentrant	
Parameters (in):	GroupAdc_SetupResultBuffer.Group	Numeric ID of requested ADC channel group.
	DataBufferPtrAdc_SetupResultBuffer.DataBufferPtr	pointer to result data buffer
Parameters (inout):	None	
Parameters (out):	None	
Return value:	Std_ReturnType	E_OK: result buffer pointer initialized correctly E_NOT_OK: operation failed or development error occured
Description:	Initializes ADC driver with the group specific result buffer start address where the conversion results will be stored. The application has to ensure that the application buffer, where DataBufferPtr points to, can hold all the conversion results of the specified group. The initialization with Adc_SetupResultBuffer is required after reset, before a group conversion can be started.	

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #68035: [diverse] Introduce rules defining which input parameters shall be passed per value and which ones per const reference

  Problem description:

  SWS_BSW_00186 especially states that input pointer parameters shall use the const qualifier (i.e., shall be P2CONST).

  In addition to that there shall be a SWS item that states that input parameters of integral and enum type shall be passed by value whereas input parameters of structure type shall be passed by reference.

  The various transformer SWS documents shall be adapted accordingly.
  –Last change on issue 68035 comment 4–

  Agreed solution:

  BSW UML model
  ————–
  The attachment "Changed Proposal in WP-A meeting" contains a list of changes to the APIs in the model (see column H). Afterwards all related documents (included in impact list) shall update their
  generated artifacts.

  General Requirements on Basic Software Modules
  ~~~~~~

  Introduce the following requirements prior to SRS_BSW_00371:

  SRS_BSW_xxxxx: Input parameters of scalar and enum types shall be passed as a value.
  Type: valid
  Description: All input parameters of scalar or enum type shall be passed as a value.
  Rationale:

  Use case: For example a function named <Mip>_SomeFunction with a return type of Std_ReturnType and a single parameter named SomeParameter of type uint8 is defined with the following signature:

  Std_ReturnType <Mip>_SomeFunction(uint8 SomeParameter);
  Dependencies: –
  Supporting Material: —
  ~~~~~~

SRS_BSW_yyyyy: Input parameters of structure type shall be passed as a reference to a constant structure
Type: valid
Description: All input parameters of structure type shall be passed as a reference constant structure
Rationale: Passing input parameters of structure type by value would result in additional run-time overhead due to efforts for copying the whole structure.
Use case: For example a function named <Mip>_SomeFunction with a return type of Std_ReturnType and a single parameter named SomeParameter of type SomeStructure (where SomeStructure is a struct) is defined with the following signature:

Std_ReturnType <Mip>_SomeFunction(P2CONST(SomeStructure, AUTOMATIC, <MIP>_APPL_DATA) SomeParameter);
Dependencies: –
Supporting Material: —

SRS_BSW_zzzzz: Input parameters of array type shall be passed as a reference to the constant array base type
Type: valid
Description: All input parameters of array type shall be passed as a reference to the constant array base type
Rationale: This effectively matches the behavior specified in the ISO-C:90 namely that a "declaration of a parameter as ’array of type’ shall be adjusted to ’qualified pointer to
type’".
Use case: For example a function named <Mip>_SomeFunction with a return type of Std_ReturnType and a single parameter named SomeParameter of type array of uint8 is defined with the following signature:

Std_ReturnType <Mip>_SomeFunction(P2CONST(uint8, AUTOMATIC, <MIP>_APPL_DATA) SomeParameter);
Dependencies: –
Supporting Material: —

General Specification of Transformers
~~~~~~

In SWS_Xfrm_00036 change
~~~~~~

const <type>* dataElement

to

<paramtype> dataElement

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

In SWS_Xfrm_00038 change

[<type> data_1,] ...
[<type> data_n]

to

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

In SWS_Xfrm_00040 change

[<originalData1>, ...
<originalDataN>]

to

[<paramtype> originalData1,] ...
[<paramtype> originalDataN]

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

In SWS_Xfrm_00044 change

<type> *data_1, ...
<type> *data_n

to

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

Speci?cation of SOME/IP Transformer
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

In SWS_SomeIpXf_00138 change

const <type>* dataElement

to

<paramtype> dataElement

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

In SWS_SomeIpXf_00141 change

[<type> data_1,] ...
[<type> data_n]

to

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy,
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

In SWS_SomeIpXf_00145 change

<type> *data_1, ...
<type> *data_n

to

[<paramtype> data_1,] ...
[<paramtype> data_n]

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

The following paragraph shall then be removed:

For the arguments of ClientServerOperation which are handed over to the transformer as data_1, ..., data_n the requirements to API parameters stated in chapter API Parameters of [5, SWS RTE] are valid (especially [SWS_Rte_01017], [SWS_Rte_01018] and [SWS_Rte_05107]).

Specification of COM Based Transformer
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

In SWS_ComXf_00007 change

const <type>* dataElement

to

<paramtype> dataElement

and add the following to the where clause after the API table after the bullet "type is data type of the data element
"

<paramtype> is derived from <type> according to the parameter passing rules rules defined by the SRS BSW General (see SRS_BSW_xxxxx, SRS_BSW_yyyyy, and SRS_BSW_zzzzz) and SWS BSW General (see SWS_BSW_00186 and SWS_BSW_00187).

Specification of Time Sync over Ethernet
~~~~~~

In SWS_EthTSyn_00040 make the parameter DataPtr of EthTSyn_RxIndication const.

Specification of SWS FlexRay Interface
~~~~~~

Change SWS_FrIf_05073 from
FrIf_NumOfStartupFramesPtr (IN)
to
FrIf_NumOfStartupFramesPtr (OUT)

Specification of ADC
~~~~~~
~[SWS_Adc_00419] Adc_SetupResultBuffer: change Adc_ValueGroupType* to const Adc_ValueGroupType*
~[SWS_Adc_00369] Adc_ReadGroup: move Adc_ValueGroupType * from Parameters (in) to Parameters (out)
~~~~~~

There is no need to change parameter from IN to INOUT in Adc_SetupResultBuffer

Specification of Com
~~~~~~
Change type of parameter MetaData of Com_TriggerIPDUSendWithMetaData from uint8* to const uint8*

Specification of ComM
~~~~~~
no change required

Specification of Dem
~~~~~~
no change required

Specification of DLT
~~~~~~
no change required

Specification of DoIP
~~~~~~
From:
Std_ReturnType <User>_DoIPRoutingActivationConfirmation(boolean* Confirmed, uint8* ConfirmationReqData, uint8* ConfirmationResData)
Std_ReturnType <User>_DoIPRoutingActivationAuthentication(boolean* Authenticated, uint8* AuthenticationReqData, uint8* AuthenticationResData)

To:
Std_ReturnType <User>_DoIPRoutingActivationConfirmation(boolean* Confirmed, const uint8* ConfirmationReqData, uint8* ConfirmationResData)
Std_ReturnType <User>_DoIPRoutingActivationAuthentication(boolean* Authenticated, const uint8* AuthenticationReqData, uint8* AuthenticationResData)

Specification of E2ELibrary
~~~~~~
no change required

Specification of Eth
~~~~~~
no change required

Specification of EthIf
~~~~~~
no change required

Specification of EthSwitchDriver
~~~~~~
no change required

Specification of ICUDriver
~~~~~~
SWS_Icu_00201: Icu_StartTimestamp
Parameter (IN): Icu_ValueType* BufferPtr shall be changed to Parameters (out) type

Specification of LdCom
~~~~~~
[SWS_LDCOM_00027]: LdCom_CopyTxData
BufReq_ReturnType LdCom_CopyTxData(PduIdType id, const PduInfoType* info, RetryInfoType* retry, PduLengthType* availableDataPtr) shall be changed to
BufReq_ReturnType LdCom_CopyTxData(PduIdType id, const PduInfoType* info, const RetryInfoType* retry, PduLengthType* availableDataPtr)

[SWS_LDCOM_00036]: Rte_LdComCbkCopyTxData_<sn>
BufReq_ReturnType Rte_LdComCbkCopyTxData_<sn>(const PduInfoType* info, RetryInfoType* retry, PduLengthType* availableDataPtr) shall be changed to
BufReq_ReturnType Rte_LdComCbkCopyTxData_<sn>(const PduInfoType* info, const RetryInfoType* retry, PduLengthType* availableDataPtr)

Specification of Lin
~~~~~~
PduInfoPtr needs to be const in Std_ReturnType Lin_SendFrame(uint8 Channel, const Lin_PduType* PduInfoPtr)

Specification of PduR
~~~~~~
* PduR_<User:LoTp>CopyTxData
add const to "RetryInfoType* retry"

Specification of J1939Nm
~~~~~~
Change parameter ’name’ of User_AddressClaimedIndication to type ’const uint8*’

Specification of SoAd
~~~~~~
=> everything already fixed with RfC 65633

Specification of SPIHandlerDriver
~~~~~~
==> nothing to change for SWS SPI

Specification of SynchronizedTimeBaseManager
~~~~~~
"StbM not affected. All issues listed in the WP-A attachment have been already implemented by IT 69124 in context of RfC 65633"

Specification of TcpIp
~~~~~~
~[SWS_TCPIP_00040] TcpIp_DhcpReadOption: change DataPtr from (IN) to (OUT)
~[SWS_TCPIP_00189] TcpIp_DhcpV6ReadOption: change DataPtr from (IN) to (OUT)
=> everything else already fixed with RfC 65633

Specification of TimeSyncOverFlexRay
~~~~~~
"Change SWS_FrTSyn_00064: parameter versioninfo of type Std_VersionInfoType* is marked wrongly as IN. Change to OUT"

Specification of EFX
~~~~~~

~~~~~~~~~~~~~~~~~~~~~~
~ [SWS_Efx_00355] Efx_Debounce_u8_u8: Include constant for pointer Input-parameter as like below.
uint8 Efx_Debounce_u8_u8(boolean X, Efx_DebounceState_Type * State, const Efx_DebounceParam_Type * Param, sint32 dT)

~ [SWS_Efx_00376] Efx_MedianSort: The parameter <InType>* Array should be InOut instead of In parameter as like below.
Parameters (in): N Size of an array
Parameters (inout): Array Pointer to an array

~ [SWS_Efx_00309] Efx_RampCheckActivity: Include constant for pointer Input-parameter as like below.
boolean Efx_RampCheckActivity(const Efx_StateRamp_Type* State_cpst)

~ [SWS_Efx_00307] Efx_RampGetSwitchPos: Include constant for pointer Input-parameter as like below.
boolean Efx_RampGetSwitchPos(const Efx_StateRamp_Type* State_cpst)

~ [SWS_Efx_00193] Efx_Array_Average: Include constant for pointer Input-parameter as like below.
<OutType> Efx_Array_Average_<InTypeMn>_<OutTypeMn>(const <InType>* Array, uint16 Count)

Specification of MFL
~~~~~~~~~~~~~~~~~~~~~~
~ [SWS_Mfl_00192] Mfl_Debounce_u8_u8: Include constant for pointer Input-parameter as like below.
boolean Mfl_Debounce_u8_u8(boolean X, Mfl_DebounceState_Type* State, const Mfl_DebounceParam_Type* Param, float32 dT)

~ [SWS_Mfl_00266] Mfl_DebounceInit: The parameter Mfl_DebounceState_Type* State should be Out instead of In parameter as like below.
Parameters (in): X Initial value for the input state
Parameters (out): State Pointer to structure for debouncing state variables

~ [SWS_Mfl_00246] Mfl_HystDeltaRight_f32_u8: Include constant for pointer Input-parameter as like below.
boolean Mfl_HystDeltaRight_f32_u8(float32 X, float32 Delta, float32 Rsp, const uint8* State)

~ [SWS_Mfl_00285] Mfl_MedianSort_f32_f32: The parameter Array should be

InOut instead of In parameter as like below.
Parameters (in): N Size of an array
Parameters (inout): Array Pointer to an array

~ [SWS_Mfl_00037] Mfl_PT1SetState: The parameter State_cpst should be Out instead of In parameter as like below.
Parameters (in): X1_f32 Initial value for input state
Y1_f32 Initial value for output state
Parameters (out): State_cpst Pointer to internal state structure

~ [SWS_Mfl_00225] Mfl_RampCheckActivity: Include constant for pointer Input-parameter as like below.
boolean Mfl_RampCheckActivity(const Mfl_StateRamp_Type* State_cpst)

~ [SWS_Mfl_00223] Mfl_RampGetSwitchPos: Include constant for pointer Input-parameter as like below.
boolean Mfl_RampGetSwitchPos(const Mfl_StateRamp_Type* State_cpst)
–Last change on issue 68035 comment 135–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.14 Specification Item SWS_Adc_00426

Trace References:

none

Content:

If development error detection for the ADC module is enabled and the the priority mechanism is disabled and the queuing is disabled: when called while any of the groups, which can be implicitly stopped, is not in state ADC_IDLE and not in state ADC_STREAM_COMPLETED, the function Adc_StartGroupConversion shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

Inconsistencies in SWS with semantics of Default errors
–Last change on issue 59085 comment 26–

Agreed solution:

solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

Notes:
- It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.15 Specification Item SWS_Adc_00427

Trace References:

none

Content:

If development error detection for the ADC module is enabled and the the priority mechanism is enabled: when called while a group, which can be implicitly stopped, is not in state ADC_IDLE and not in state ADC_STREAM_COMPLETED, the function Adc_StartGroupConversion shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-
  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

  SWS_LinIf:
  ———-
  SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.16 Specification Item SWS_Adc_00428

Trace References:

none

Content:

If development error detection for the ADC module is enabled and the the priority mechanism is disabled and the queuing is enabled: when called while a group, which can be implicitly stopped, is not in state ADC_IDLE and not in state ADC_STREAM_COMPLETED, the function Adc_StartGroupConversion shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of 'Runtime errors'

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another.

Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.17 Specification Item SWS_Adc_00433

Trace References:

none

Content:

If development error detection for the ADC module is enabled: if called while group is not in state ADC_IDLE, function Adc_SetupResultBuffer shall raise development report a runtime error ADC_E_BUSYand return without any action.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of 'Runtime errors'

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-
  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

  SWS_LinIf:
  ———-
  SWS_LinIf_00359: add Det_ReportRuntimeError

  SWS_UdpNm:
  ———-
  Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

  *** ECUC XML ***
  Not affected. No configuration of runtime error reporting required (see SWS BSW General).
  –Last change on issue 59085 comment 88–

  BW-C-Level:

Application	Specification	Bus
1	4	1

1.18 Specification Item SWS_Adc_00487

Trace References:

none

Content:

In case development error reporting is activated:

The API shall report the DET a runtime error ADC_E_NOT_DISENGAGED in case this API is called when one or more HW channels (where applicable) are in a state different then IDLE (or similar non-operational states) and/or there are still notification registered for the HW module channels.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of 'Runtime errors'

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification "belongs".

  *** BSW UML Model ***
  SWS_CanNm:
  ———-
  Chapter 8.6.1 Optional Interfaces:
  Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.19 Specification Item SWS_Adc_00489

Trace References:

none

Content:

In case development error reporting is activated:

The API shall report the DET a runtime error ADC_E_TRANSITION_NOT_POSSIBLE in case the requested power state cannot be directly reached from the current power state.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

Notes:
- It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.20 Specification Item SWS_Adc_00497

Trace References:

none

Content:

In case development error reporting is activated:

The API shall report the DET error ADC_E_POWER_MODESTATE_NOT_SUPPORTED in case this API is called with an unsupported power state is requested or the peripheral does not support low power states at all.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #77727: [ADC] ADC_E_POWER_MODE_NOT_SUPPORTED is a duplicate of ADC_E_POWER_STATE_NOT_SUPPORTED

  Problem description:

  ADC_E_POWER_MODE_NOT_SUPPORTED is a duplicate of ADC_E_POWER_STATE_NOT_SUPPORTED error code and is basically useless.

  ADC_E_POWER_MODE_NOT_SUPPORTED appears in one requirement only:
  [SWS_Adc_00497]
  In case development error reporting is activated:
  The API shall report the DET error ADC_E_POWER_MODE_NOT_SUPPORTED in
  case this API is called with an unsupported power state is requested or the peripheral
  does not support low power states at all.
  ()

  [SWS_Adc_00488]
  In case development error reporting is activated:
  The API shall report the DET error ADC_E_POWER_STATE_NOT_SUPPORTED in
  case this API is called with an unsupported power state or the peripheral does not
  support low power states at all.
  ()

  SWS_Adc_00497 is a duplicate of SWS_Adc_00488

  Proposal: remove SWS_Adc_00497

  Agreed solution:

  SWS_Adc_00497 should be changed to:

[SWS_Adc_00497]
In case development error reporting is activated:
The API shall report the DET error ADC_E_POWER_STATE_NOT_SUPPORTED in case this API is called with an unsupported power state is requested or the peripheral does not support low power states at all.
–Last change on issue 77727 comment 8–

BW-C-Level:

Application	Specification	Bus
1	1	1

1.21 Specification Item SWS_Adc_00498

Trace References:

none

Content:

In case development error reporting is activated:

The API shall report the DET a runtime error ADC_E_TRANSITION_NOT_POSSIBLE in case the requested power state cannot be directly reached from the current power state.

All asynchronous operation, needed to reach the target power state, can be executed in background in the context of Adc_Main_PowerTransitionManager.

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

  Inconsistencies in SWS with semantics of Default errors
  –Last change on issue 59085 comment 26–

  Agreed solution:

  solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

  Notes:
  - It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
  - The review task of the ITs shall be done by the WP to which the specification

"belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1

1.22 Specification Item SWS_Adc_00530

Trace References:

none

Content:

RfCs affecting this spec item between releases 4.3.0 and 4.3.1:

- RfC #59085: Rollout of ’Runtime errors’

  Problem description:

Inconsistencies in SWS with semantics of Default errors
–Last change on issue 59085 comment 26–

Agreed solution:

solution in Column "G" of the new attachment https://www.autosar.org/bugzilla/attachment.cgi?id=4604

Notes:
- It is not enough just to migrate the error from one classification table to another. Please also check the related requirements (and background information) which is referring to that error and adapt them if needed.
- The review task of the ITs shall be done by the WP to which the specification "belongs".

*** BSW UML Model ***
SWS_CanNm:
———-
Chapter 8.6.1 Optional Interfaces:
Add within SWS_CanNm_00325 the API function Det_ReportRunTimeError

SWS_LinIf:
———-
SWS_LinIf_00359: add Det_ReportRuntimeError

SWS_UdpNm:
———-
Replace UDPNM_E_NO_INIT with UDPNM_E_UNINIT in description of API UdpNm_MainFunction_<Instance Id> (SWS_UdpNm_00234)

*** ECUC XML ***
Not affected. No configuration of runtime error reporting required (see SWS BSW General).
–Last change on issue 59085 comment 88–

BW-C-Level:

Application	Specification	Bus
1	4	1